

**TEST REPORT**

Date: March 1, 2018

Company: Nawoo Ltd

Test Report ND8

We hereby certify that samples of the material identified below by batch number, have been analyzed in accordance with test methods that meet and/or exceed the detection limits for fluoride, chloride, and sulfur per ASME Boiler and Pressure Vessel Code, Section V, Article 6, paragraph T-641, 1998-2017 Editions and Addenda with the following results:

SAMPLE		RESIDUE	FLUORIDE	CHLORIDE	SULFUR
PICO COLOR CHECK DEVELOPER BATCH NO.	NPD-4 18NPD19	11.0871G	<0.0001%BW	<0.0001%BW	<0.0001%BW

SHERWIN INCORPORATED



Robert Siegel  
Laboratory Director